





Milking barn and water storage - 6/2012



Milk barn with outdide wall restored and foundation reinforced - note deteriorated



Milk barn -Exterior walls upgraded - Eroded walkway- and deteriorated roof



Milking cows in pasture



Mílk barn - Upgraded exterior wall



Deteriorated floor, rafters, and roof



Milk barn -Exterior walls upgraded - 6/2014



Milk barn - New windows and outer walls